



This steamboat operates from a stone quay without fenders. When coated with conventional paints the topsides required repainting halfway through the season but when Timberseal PS and UC were applied the paintwork was still in good condition at the end of the season.